



60DegreeV6
The best source for all
your GM 60° V6 needs

User Name Password Help Register
☐ Remember Me?

Home Forum Gallery Garage Groups Links/Downloads What's

Site News 60° V6 Family Tree CR Calculator Advanced Search

[Home](#)
[1980-1995 Iron Head](#)
[Complete 1995 GM 3.4L Engine Teardown and Rebuild Project](#)



[The New 2013 Audi S6](#) Learn More About The New 2013 Audi S6. Heighten Every Moment. www.AudiPerformanceCars.com/S6

[Golf Cart Parts Cheap](#) All Parts for all Carts, Low prices Parts and service manuals www.lvssales.com

[Toyota Rav4 Specs](#) Shop w/Cars.com To Access All The Info You Need About Your New Toyota Cars.com/Toyota/RA AdChoices ▶

[Interested in Pontiac G8?](#) Looking For a Pontiac G8? Why Not Consider a Chevy Camaro? Get Info. www.Chevrolet.com/Camaro

[GMC Supplier Discounts](#) Find Supplier Discounts on Most GMC Models. See Site for Details. www.GMSupplierDiscount.com/GMC

[Online Computer Degree](#) Personal - Supported - Streamlined. Apply For Our October 22nd Term. IvyBridge.Tiffin.Ed AdChoices ▶

If this is your first visit, be sure to check out the [FAQ](#) by clicking the link above. You may have to [register](#) before you can post: click the register link above to proceed. To start viewing messages, proceed to the Forums area and select the forum that you want to visit.

 **Menu**

60° V6 Family Tree
1980-1995 Iron Head
1987-1994 Aluminum Head MPFI
1993-Present Aluminum Head SFI
1991-1997 DOHC
2004-Present DOHC VVT
2006-Present Pushrod VVT
Transmissions
General Information
Computers
Myths
CR Calculator

Complete 1995 GM 3.4L Engine Teardown and Rebuild Project

Published on 11-16-2010 05:32 PM

For the better part of a year, I have been fully engaged in the complete tear down and rebuild and performance upgrade of a 1995 GM L-32 3.4L OHV RWD V6 engine. I have been trying to faithfully document all phases of these procedures in digital photographs that I have saved for public consumption on the following image warehouse site:

<http://www.photobucket.com>

...accessible to all by using my 60degreev6.com nickname of:

60dgrzbelow0

The deconstruction images show the poor condition of the engine after 100,000 miles of hard wear and tear and the re-build images include all views of the tools required, the necessary machining work, new parts, factory and performance part numbers and many other aspects of the re-build that may prove helpful to many thinking about doing this full-scale job. I often ask questions of those having greater knowledge and understanding than I might about this motor and I am also happy to answer any questions and/or share and provide information either here in the forum or via my email address of:

at60dgrzbelow0@yahoo.com

I hope this effort will be contributory to the site.

Sincerely,

Bob

-- #107

[Contact Us](#) [Archive](#) [Top](#)

All times are GMT -4. The time now is 12:59 AM.

Powered by [vBulletin®](#) Version 4.1.10

Copyright © 2012 vBulletin Solutions, Inc. All rights reserved.

Donation System provided by [vBDonate \(Pro\) v1.0.0 \(BETA 0\)](#) - [vBulletin Mods & Addons](#). Copyright © 2012 DragonByte Technologies Ltd.
Easy Article Management provided by [Easy Article Management v1.0.0](#) - [vBulletin Mods & Addons](#). Copyright © 2012 DragonByte Technologies Ltd.

© 2000-2012, 60DegreeV6.com

Sphinx-based search by [Digital Point](#)

Page Time: **0.19229** seconds Memory: **11,882** KB Queries: **58** Templates: **31**
Server Uptime: **59 days 14 hours 57 mins** Server Load: **0.35** : 0.23 : 0.19